Bruhath Bangalore Mahanagara palike,

Inspection Report

1	Name of work	Drilling of borewell and erecting pump and motor and providing electrification near bus stand at Jalahali villag
2	Administration Approval & Date	JC/RRNZ/AS/2953/2013-14 Dtd.05-03-2014 by JC (RRNZ)
3	Technical Sanction Estimate No.& Date	EE/RRND/TS/14/2014-15 Dtd: 16-06-2014 by EE(RRND)
4	Estimate Amount	Rs.6.00Lakhs
5	Job Code No.	016-14-000031
6	P-Code	P-2178
7	Agreement No & date	EE/RRND/AG.No./34/2014-15 Dtd.20-06-2014
8	Work order Number & Date	EE/RRND/Wo.No./34/2014-15 Dtd.20-06-2014
9	Contract Amount as per Agreement	Rs. 6,00,000/-
10	Bill Amount	Rs.665428 /- including KRIDL Charges
11	B.R. No. & Date	283/2014-15 Dtd: 31-7-2014
12	Agency	KRIDL, Bangaluru
13	M.B. Number & Page No. of Measurement recordes	1812/14-15 Pages 181101 to 181108 (Xerox Copy of MB)
14	Date of Inspection	1-1-2016
15	Enclosures	1) 2 Number of photos taken during inspection
16	Inspection Report	I have Inspected the above site along with the Concerned person. It is observed that one bore Cole has been drilled and is Connected to the System for providing Drinking water to the residents of the area. This is a reference to the Xerox Copy of MB No 1812

EE (RRND) RR Nagara Zone

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ರಾಜರಾಜೇಶ್ವರಿ ನಗರ ವಿಭಾಗ

(R.Sathyanarayana)
Inspection Report officer,